
Transboundary Spill NPDES GA0108928 Order No. R9-2014-0009, Amended by R9-2014-0094		
Type $A_B = 17/8 $ (CAL OES 1-800-852-7550)		
Name of Person Reporting Spill Carlos Pena		
Telephone No. of Person Reporting 619-210-1370		
Spill Location/Name Tijuana River at the International Boundary		
GPS Coordinates 32.32.30 N, 117.2.18 W		
Spill Reached:Drainage ChannelDrainage StructureXXXSurface Water		
Spill Reached:MS4		
Vol Spill to MS4Vol Recovered from MS4		
Estimate Spill Volume from All Sources Approx. 1,185,000 Gallons		
Volume That Reached: Surface Water, Drainage Channel, Not Recovered from MS4 Approx. 1,185,000		
Gallons		
Total Recovered Volume 0		
Number of Spill Appearance Points1		
Appearance Descriptions Turbid Water		
Spill Flow: Start Date 02/25/18 Start TimeApproximately 2100		
Notification: Date02/26/18 Time0300		
Operator Arrival: Date <u>02/25/18</u> Time <u>2100</u>		
Spill Flow: End Date 02/26/18 End Time 0300		
Cleanup Completed: Date NA Time		
Probable Cause of Spill Electro-Mechanical Failure at Pump Station CILA		
Notification of CAL OES Date 02/027/18 Time 1215		
CAL OES Control Number 18- 1288 Daniel Phillips		
Description of Spill Flow DestinationTijuana River Channel		
Spill Flow Cause Electro-Mechanical Failure at Pump Station CILA		
Spill Flow Failure Point Pump Station CILA		
Spill Flow Storm EventN/A		
Spill Corrective ActionsNone		
Spill Flow Response ActionsNone		
Spill Flow Completion Date 02/26/18		
InvestigationN/AReasonsCompletion Date		
Health Warnings Posted YesxNo		
Name of Beaches Impacted:NoneSurface Water Impacted:Tijuana River		
Location and No. Of Samples Collected (Type A)N/A Number		
Parameters TestedN/A		
Regulatory Agencies Receiving ResultsN/A`		
Methodology for Spill Volume Estimate Flow Rates at UISBWC Metering Station		
Amount of Spill Recovered		
I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a		
system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the		
best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information,		
including the possibility of fine and imprisonment for knowing violations. Contribution Official Control Page 17.118 Area Operations Manager 17.118 02/27/18		
Certifying Official Carlos Pena Title Area Operations Manager Date 02/27/18 CARLOS DENIA Digitally signed by CARLOS PENA		
Signature CARLOS PENA Date: 2018.02.27 12:24:47 -08'00'		



US Section, IBWC

Tijuana River Gage



Data Set Export - Discharge Total.US Gal	
Hourly@11013300	
Timestamp (UTC-	Value (US
08:00)	Gallons)
2/25/2018 20:00	0
2/25/2018 21:00	0
2/25/2018 22:00	59384
2/25/2018 23:00	249083
2/26/2018 0:00	329912
2/26/2018 1:00	242485
2/26/2018 2:00	178152
2/26/2018 3:00	110520
2/26/2018 4:00	14846
2/26/2018 5:00	0
2/26/2018 6:00	0
2/26/2018 7:00	

1184383

Total